

How to Ace K Transition Surfaces?

Posted by paulofern - 2016/08/23 15:28

Hi, Guys....

Please, Is there anybody out there that could help in master k transition corners in G2? How can I fillet that model?

https://s15.postimg.io/42s5zp9y3/k_Transition_Fillet.jpg

The wire model is at http://s000.tinyupload.com/?file_id=00851448007744138826

Thanks for You help

=====

How to Ace K Transition Surfaces?

Posted by asanty - 2016/08/23 19:11

Tutorial example <https://www.youtube.com/watch?v=qCKOx5BJ8V0>

=====